



JON M. HUNTSMAN, JR.
Governor
GARY R. HERBERT
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report

Minerals Regulatory Program

Date: May 28, 2009

Reviewed: PRB

Mine Name: Brown's Canyon Rock Quarry 1	Permit Number: M/043/0017
Operator Name: Rock Products of Utah, Inc.	Inspection Date: 05/20/2009
Inspector(s): Brett Gregory for Leslie Heppler	Time: 10:30 am
Other Participants: Develon Worth	Mine Status: Active

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Soils	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
10. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Bond Renewal Date: 04-18-2011 **Bond Amount:** \$83,100 **Permit fee:** \$1000 delinquent (2008 & 2009). (Note- fees for 2009 are also due in July)

Purpose of Inspection: The previous inspector suggested the area be checked for any acreage over and above the bonded amount in the permit. I went to GPS the area for this information and pass it on to the new lead inspector.

Inspection Summary: (Photos attached)

- 1) The permit fees have not been paid for the year 2008 and 2009. The bond is inadequate for the acreage evaluated with the GPS (22 acres) and the bond will need to be escalated (current average price for 22 acres is \$104,400) and amended for an additional two acres (mainly to the northeast and northwest sections of the mining operation).
- 2) Mr. Worth was asked about the oil barrels still on site (as per the previous inspection) and comments were made suggesting that the storage shack shown in the pictures below were for containment purposes, and that a number of the excess barrels were slated to be removed from the site within the month. DOGM requested the operator to pick up loose trash around the perimeter and he said that he would do so.
- 6) Mr. Worth displayed some concern about the bond amount per acre and wanted to know if the amount the division was asking would go down for the economic downturn in the economy. I suggested to him that he do concurrent reclamation of the mined-out areas to reduce the amount of bond he needs to provide the division.

- 9) DOGM checked the area for any soil stockpiles and did not find sufficient material that would be needed to perform concurrent reclamation. As per regulation R647-4-107-5 it is suggested that any suitable soil be stockpiled for reclamation.

Conclusions and Recommendations: Mr. Worth needs to provide the division with adequate bonding for the acreage he is over in the current permit or commence reclamation immediately. All permit fees should be paid or an inactive and/or suspension status will be applied. DOGM will continue to inspect this site when in the area.

Inspector's Signature

BG:vs

cc: Develon Worth

Attachemnt GIS

O:\M043-Summit\M0430017-BrownsCynRock-RockProducts\inspections\insp-05202009.doc

09-09-09



Containers in question.




Loose trash to be removed.



Loose trash to be removed.



Defunct Machinery to be removed




Mine Number: M0430017
Mine Name: Brown's Canyon Rock Quarry
Township 01 S Range 05 E Section 20 SLBM

Inspection Date May, 20, 2009
 Map Produced by DKS

Acres Disturbed	21.37
Acres Seeded	0
Road Acres Disturbed	0
Total Acres Disturbed	21.37
Acres Released	0
Acres Excluded	1.2
Acres PreExisting	0
Acres Prelaw	0

- Legend**
 All items symbolized in legend may not be appear on map
- Acres
 - Mine
 - Section Line
 - Other
 - County Boundary
 - Interstate
 - US Route
 - State Route
 - Primary Road
 - Secondary Road
 - Main Dr. Road
 - Underpass Road
 - Interchange
 - Trail
 - Township or Range Line
 - Township or Range Line location doubtful
 - Section Line location doubtful
 - Barred Area
 - UTLA Mineral Leases
 - BLM Leases
 - Conserved
 - Reclaimed
 - Reforested
 - Grassland
 - PreExisting
 - Prelaw
 - Community Pl

DOQ imagery date 2006



Dept. of Natural Resources
 Division of Oil, Gas, and Mining
 Mineral Mines Program

1:2,100 1 inch = 175 feet
 Verify Scale
 Different data sources and input scales
 may cause misalignment of data layers.
 This product may not meet DOGM
 standards for accuracy and content.